

## OHIO STATE UNIVERSITY 2009 MILLIKIN ROAD COLUMBUS, OHIO 43210

## FOR WORK ON:

OSU Marion Morrill Hall

## **WORK INCLUDES:**

- Extensive Site Protection
- Demolition of Concrete Walks & Steps
- Installation of New Concrete Walks & Steps
- Caulking Replacement
- Cleaning of Masonry
- Extensive Concrete Repair
- Spot Tuckpointing
- Spot Brick Replacement
- Brick Repair
- Louver Replacement
- Window Modifications
- Ceiling Repair
- Ceiling Replacement









