



UNION STATION ASSOCIATION
532 W. CENTER STREET
MARION, OHIO 43302

FOR WORK ON:

**Historic Erie Railroad
Caboose Car**

WORK INCLUDES:

- Extensive Site Protection
- 100% Paint Removal
- Sheet Metal Repair
- Painting to Historic Colors
- Extensive Exterior Painting
- Extensive Exterior Details
- Extensive Window Modifications

